

COPY

Ship's name

"SALAMMANNA"

Port

L.A.
L.A.5638
No. 5816

Last survey date

Class is subject to

(See End of 18.12.62)

- 1) The auxiliary condenser water box being examined at the earliest opportunity.
- 2) The repairs which have been carried out to the port and centre furnaces of the port boiler being examined by one of the Society's Exclusive Surveyors at the earliest opportunity.

From above reports and certificates Port of France 19.6.62, it is concluded that an MBS has been carried out. It is not clear whether the remote controls were examined but as the same surveyor carried out a Safety Equipment Survey (see letter of 2.8.62) this would have been examined at that time.

IT IS SUBMITTED that this vessel will be eligible for the record of MBS 6.62 when the subject item as detailed in No. 2 above has been dealt with.
Subject as above.

Advise Owners further to
letter of 19.12.62.



© 2021

Lloyd's Register
Foundation