

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

19th December, 1962.

C
AH/HW

Dear Sirs,

Steamer "SALAMMANNA"

The class of this ship is subject to:-

- (1) Indented shell plate in way of No.4 hold starboard side and structure in way being examined and dealt with as necessary at the next drydocking.
- (2) The auxiliary condenser water box being examined at the earliest opportunity.
- (3) The repairs which have been carried out to the port and centre furnaces of the port boiler being examined by one of the Society's Exclusive Surveyors at the earliest opportunity.

It is considered that item No.3 should receive attention as soon as possible and I shall be glad if you will kindly ascertain and let me know what arrangements the Owners propose to make in this respect.

I have also to point out that a Boiler Survey became due at the end of July, 1962 and the Owners' proposals in this respect also are desired.

Yours faithfully,

Messrs. N. & J. Vlassopoulos Ltd.,
Bevis Marks House,
Bevis Marks.
LONDON, E.C.3

Deputy Clerk to the
Classification Committee.

Lloyd's Register
Foundation

004698 - 004702 - 0083