

Ship's name *SALAMANNA*Port *RIO*No. *9602*

Class is subject to —

Last survey date *25.5.64*

- (1) *Iron Condenser water box being examined at the earliest opportunity*
- (2) *Starboard furnace of port boiler being specially examined and checked by 2/64 (MBS record 9/63 being withheld)*

MBS due 6/63, commenced 9/63.

SRL *Item examined, calibrations taken. No previous furnace calibrations on board. The Owners requested repairs be deferred until such time as a decision reached regarding the future of the ship on account of shell damage sustained by previously.*

The Surveyor recommends the ~~starboard~~ furnace port boiler outboard furnace be repaired or renewed by 7/64 (3 mos limit)

It is submitted that the vessel WILL BE eligible for the record MBS 9/63 when the survey has been completed, ~~by~~

*Subject as above re Item (1)
and as now amended re Item (2)*

To Complete MBS *Subject item to be dealt with*