

28 AUG 1963

Ship's name "SALAMMANNA"

Port

Suz

No. 1892

GB Class is subject to For conditions of Last survey date 29.7.63.  
endorsement.

S.R.L. Appendix (as before ~~xxxxnone~~)

Nature of present survey (afloat and ~~in drydock~~)

Wear and tear and part subject item repairs.

Recommendation

SUBJECT to indented shell plate in way of No.4 hold (s.s) and structure in way and to indented sheerstrake and plating in 1st below in way of No.3 hold (s.s) also to indented shell plate in 'A' strake in way of No.6 D.B.tank (s.s) and keel plates aft being specially examined and dealt with as necessary next drydocking, and to shell plate in way of No.1 hold bilge (p.s.a) (cement box fitted) being specially examined and dealt with as necessary next drydocking, but without other conditions.

As Now. Subject  
Without.

IN S.R.L. APPENDIX.

Indents in side shell plating (p & s).  
Poop side (p.s) indented.

End. S.1

004698-004702-0137

Lloyd's Register  
Foundation

*James*  
28/8/63  
X