

EA

24 APR 1963

Ship's name "SALAMMANNA"

Port CCO.

No. 6693

Last survey date 1.2.63.

Class is subject to

indented shell plate in way of No.4 hold (s.s)  
and structure in way being specially examined  
and dealt with as necessary at the next drydocking.

S.R.L. Appendix (as before ~~XXXXXXX~~  
~~or none~~)


Nature of present survey (~~afloat and in drydock~~  
~~XXXXXXXXXX~~)

Docking: Deferred repairs to damage caused by contact.

Recommendation SUBMITTED record of DS 2,63 be assigned,  
subject as above and to indented sheerstrake and  
plating in 1st below in way of No.3 hold (s s),  
also to indented shell plate in 'A' strake in  
way of No.6 D.B. tank (s.s.) and keel plates aft  
being specially examined and dealt with as necessary  
next drydocking.

DS 2,63 Subject

IN S.R.L. APPENDIX  
~~Indents in side shell plating (p & s).~~  
~~Poop side (p.s) indented.~~



© 2021

Lloyd's Register  
Foundation

*Handwritten:* 17.2.63