

115 FEB 1955

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"SANGOLA"

REPORT

Cal. No. 16340

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

There is an Endorsement of Class (B).

This ship stranded, broke her back and suffered extensive damage in July, 1953.

The CALCUTTA Surveyors report 11,54, this ship placed in drydock and due to damages from various causes, as above, extensive repairs effected to shell, deck and bulkhead plating, structure in D.B. tanks, superstructure and other items.

Concurrently with the above the requirements of a SPECIAL SURVEY (B) due 8,55 have been complied with.

IT IS SUBMITTED the ship is eligible to have record of docking 10,54 and notation of "ss. Cal. 11,54" assigned as recommended.

10,54 Cal.
ss. Cal. 11,54.

DELETE ENDORSEMENT OF CLASS (B)

ABM.
9-2-55



© 2021

Lloyd's Register
Foundation

004698-004702-0281