

Lloyd's Register of Shipping,

Saint John, N.B.

P. O. Box 658

April 29, 1944.



The Secretary,
Lloyd's Register of Shipping,
Wokingham, Berks.

Dear Sir:-

While checking over the equipment intended for the standard 4700 ton cargo vessels building in this district, it was found that two Bower Anchors (Certificates Nos. 3894 and 3895) allocated for S.S. "FAWKNER PARK" (Hull 16), and as shown on Saint John Report No. 546, had not been placed on board.


Mr. R. M. Scott, recently transferred from this port, and who verified the equipment before being shipped, was communicated with and it was subsequently confirmed from the Builders that two Bower Anchors (Certificates Nos. 8715 and 8716) intended for a sister ship had inadvertently been placed on board Hull 16.

The corrected particulars of the two Bower Anchors for S.S. "FAWKNER PARK" are enclosed and I would be pleased if you would modify the First Entry Report accordingly.

I am, Dear Sir,

Yours faithfully,

Enc.
JT/D



© 2020
for the Surveyors.

Lloyd's Register
Foundation

H

M
f.c.8

rel

2 JUN 1944

Ack St. J in ref:—

6/6



© 2020

Lloyd's Register
Foundation