

 M.V. BRITANNIC

This ship was built in 1930 and the toes have not been examined.

However the repairs to No 8 crank of the 10 cylinder engine are not expected to have any significant effect upon the toes particularly in view of the impending withdrawal of this ship from service.

JLB
19.8.60



© 2021

Lloyd's Register
Foundation

004769-004777-0258