

Pt. 2,

For the information of Surveyors and the Committee only.

Received at

Office

19

Lloyd's Register of Shipping.

(Report on Machinery, No. _____ Port _____)

No. 4843.

ENGINE or BOILER VALVES or CONNECTIONS.

I have to report that the Details, as herein described, manufactured by Messrs. Chas W. Hill Ltd of Glasgow for the Engines or Boilers No. 533 being constructed by Messrs Workman Clark Ltd. of Belfast have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects.

These have been despatched to Messrs Workman Clark Ltd. Belfast.

Stamp Mark.

LLOYD'S TEST.

lbs.

No. 4843ESPChas. S. PorterGlasgow 2/5/1934

Description.

4. Plain Air Receiver Ends. 5'9" Dia X 1 3/16 Thick

4. Flange - do - do - 5'9" " X 1 5/16 - do.
with M. H. Doors fitted.Tensile Test:
per square inch.

Tests, if any.

When Inspected.

1/3/34 to 21/4/34Diameter of stays over thread 4 - Thickness 5 BWG

Working pressure of back plate by rules

004789-004798-0183