

22 NOV 1963

Ship's name "DURHAM"

Port

Lon.

No. 150439

Last survey date 15.10.63.

Class is subject to

For conditions of class see previous  
endorsement.

S.R.L. Appendix (as before ~~xxxxxxx~~)

Nature of present survey (afloat and in drydock ~~xxxxxxxxxxxx~~)

Repairs to part deferred items as above.

Recommendation

SUBJECT to No.10 keel plate from forward  
(temporarily repaired 12.61) and to indented  
shell plate H.17 (p.s. from fwd) being  
specially examined and dealt with as  
necessary by the Special Survey but  
without other condition.

As Now. Subject  
Without.

IN S.R.L. APPENDIX.

Shell plates G.7, H.4, M.17 & 18  
(p.s. from fwd) indented.

Shell plate L.9 (p.s.) indented.

No.3 hold after bulkhead (s.s.) slightly buckled.

R/S.  
13.11.63  
*[Signature]*