



# Lloyd's Register of Shipping,

united with THE BRITISH CORPORATION REGISTER.

RECEIVED

17 JUN 1958

ROTTERDAM, 16-6-1958

Westersingel 106, P.O. Box 701

Dear Sir,

"AFRICAN SKY", 00384 in the RB

This ship is at present in dry dock at Flushing for condition and damage repairs.

The Master has been informed that the boiler survey was overdue from the end of December 1957, but in reply he stated that the boilers had been surveyed in Italy in March, 1958 by the ABS Surveyors.

The ABS Surveyor was also present in dry dock at Flushing.

Mr. Auer, the Principal Surveyor at Rotterdam for ABS stated, when approached, that it is the Owners' intention to have the ship classed by ABS, but at present he has no information whether the class has been accepted by their Head Office at New York.

Meantime the following recommendations have been made to the Master:

- Rudder to be unshipped and placed in order (Badly worn bushing)
- Screwshaft to be drawn and sternbush to renew.
- Boilers to be prepared for survey.

We shall be pleased to learn at your earliest convenience whether any information has reached your office that the Owners desire the Society's class to be withdrawn.

Thanking you in anticipation, we are,

Yours faithfully,

The Secretary,  
London.



© 2020

Lloyd's Register  
Foundation

C/H

CLASSIFICATION

H BU R.A.F.

REQUESTING EARLY REPLY.

PERSON:  
THE SECRETARY:

...the ...  
...the ...  
...the ...

...the ...  
...the ...  
...the ...

...the ...  
...the ...  
...the ...

(H) INC



© 2020 Lloyd's Register Foundation



COLLECTOR

RECEIVED

Lloyd's Register of Shipping

BRITISH MARITIME