

- 8 JUL 1965

Ship's name

"ANGELIC"

Port

Mlt.

No.

16721

GB

Class is subject to

NONE

Last survey date

25.5.65.

S.R.L. Appendix (as before ~~XXXXXXXXXX~~)

Nature of present survey (afloat and ~~in drydock~~)

Examination on account of grounding and contact damage.

Recommendation

SUBJECT to set in stern counter plating and upper deck plating in way being specially examined and dealt with as necessary next drydocking but ACTION be DEFERRED for examination in dry dock after grounding.

SUBJECT

INSERT IN S.R.L.

Drydocking (grounding).

IN S.R.L. APPENDIX


Indents in shell plating (p&s).

Bottom plating slightly wavy.

OFFICE NOTE:- Bottom plating and inner bottom plating in

No. 3 hold stiffened - Rot. 11, 52.

Crack arresters fitted to upper deck beam 54-155 (p&s) - St. J. 3, 53.



© 2020

Lloyd's Register
Foundation

Handwritten signature/initials