

"ANGELIC" ~~xxxxx~~ <sup>COPY</sup>

Ship's name Ex "SEVERN RIVER" Port Ams No. 26746

174 JUN 1965

Last survey date 29.4.65.

GB Class is subject to NONE

ACTION is DEFERRED for examination in drydock  
after grounding.

S.R.L. Appendix (as before or none) ~~xxxxxxxxxx~~

Nature of present survey (afloat and in drydock) ~~xxxxxxxxxx~~

Docking. Grounding damage repairs.

Recommendation

SUBMITTED record of 'DS 4,65' be assigned.

DS 4,65

DELETE FROM S.R.L.

Drydocking (grounding).

IN S.R.L. APPENDIX

Indents in shell plating (p&s).

Bottom plating slightly wavy.

OFFICE NOTE - Bottom plating and inner bottom  
plating in No.3 hold stiffened - Rot.11,52.

Crack arresters fitted to upper deck beam

54-155 (p & s) - St.J. 3,53.

Publications Dept. to Note.