

28 NOV 1963

Ship's name "SEVERN RIVER"

Port

Gdk

No.

1388

Last survey date 25.10.63.

GB Class is subject to NONE.

S.R.L. Appendix (as before ~~XXXXXXXXXX~~)

Nature of present survey (afloat and in drydock) ~~XXXXXXXXXXXXXXXXXXXX~~

Equipment - loss of port bower anchor.

Recommendation

SUBJECT to a bower anchor being
supplied at the earliest opportunity. D

As Now. Subject

IN S.R.L. APPENDIX.

Indents in shell plating (p & s).

Bottom plating slightly wavy.

OFFICE NOTE

Bottom plating and inner bottom plating in

No.3 hold stiffened - Rot.11,52.

Crack arresters fitted to upper deck

beam 54-155 (p & s) - St.J. 3,53.