

"JAG SEVAK" - Visakhapatnam cable 26.7.65.

IT IS SUBMITTED that as the ship is aground and apparently heavily damaged the class be temporarily suspended pending permanent repairs. It is the responsibility of the Owners or their Underwriters to refloat the ship, and no survey should be carried out to assist salvage operations unless specially requested by the Owners or salvors and confirmed by Head Office who should be advised of any decision taken as to the future of the ship.

The Visakhapatnam Surveyors to be advised accordingly.


27.7.65. 



© 2020

Lloyd's Register
Foundation