

EM JUN 1965

~~xxxxxx~~

Ship's name

"JAG SEVAK"

Port

Cal.

No.

1622

Last survey date

13.3.65.

GB Class is subject to

indented shell plate 2nd below sheer
between frs.67/69 (p.s) and structure in way being specially
examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before or none) ~~xxxxxxx~~

Nature of present survey (afloat ~~xxxxxxxxdryxxxxxx~~)

Temporary repairs due to contact damage.

Recommendation


SUBJECT as above, and to indented shell
plates H.16 (p & s) from aft in way of No.1
hold and H.13 (p.s) in No.2A hold etc. being
specially examined and dealt with as necessary
by 9,65.

As Now. Subject

IN S.R.L. APPENDIX

Forecastle deck plating (p.s) indented.

✓



© 2020

Lloyd's Register
Foundation

31-5-65