

COPY

London

c.c. Karachi.

## LLOYD'S REGISTER OF SHIPPING



Port.....CHITTAGONG.....

.....9th November, 1965.....

This is to Certify that I have surveyed part of the machinery of the S.S. "MANSOOR" 4551 Gross tons of KARACHI for Boiler repairs and propeller damage stated to have been sustained by contact with a Pontoon mooring chain on the 23rd October, 1965, whilst lying afloat at Chittagong on the 22nd October, 1965, and subsequently, and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained ~~and the following survey records assigned~~ without fresh record of survey subject to the starboard boiler centre furnace back tube plate and wrapper plate, and propeller being examined and dealt with as found necessary on arrival at Karachi, where now bound via Chalna, the starboard boiler pressure meantime not to exceed 150 p.s.i., and to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:—

(A. ROSS)

Surveyor to Lloyd's Register of Shipping

## KEY TO ABBREVIATIONS

|     |                                |     |   |        |                                   |
|-----|--------------------------------|-----|---|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey        | MBS | Main Boiler Survey                          | TS     | Tailshaft Survey                  |
| CSM | Continuous Survey of Machinery | OF  | Fitted for oil fuel (date) FP above 150° F. | TS(CL) | Tailshaft Survey—Continuous Liner |
| DBS | Donkey Boiler Survey           | SGS | Steam Generator Survey                      | TSN    | Tailshaft renewed                 |
| ES  | Engine Special Survey          | SFS | Steampipe Survey                            | TS(OG) | Tailshaft Survey—Oil Gland        |

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."