

Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRS

Received London

27 MAY 1965

Ship's Name SS/MS "MANSOOR"

Gross tons 4551

Is there a rpt. 9? Yes

LR 521968

Port Karachi

Rpt. No. KRH/819

No. of visits 1

First date &

Last date 4-5-65

Interim Cert. issued
& copy herewith?

Yes

Damage rpt. issued

& copy herewith? No

Last rpt. (H.Q. only) KRH 699

Date of
completing rpt.

13-5-65

Surveyed at, if different from Port above -

Surveyed afloat
and/or in D.D.

Afloat

Last date of examination in D.D. -

Has a Load Line
Survey been held?

No

Freeboard Marks verified No

State which additional Rpt. 8 is attached: (C)/ (PS)/ (PR)/ (EQ)/ (R)/

Survey fees

Damage fee

Expenses

Rs 150/-

Rs 8/-

S.A. fee

I have surveyed the above ship in accordance with the Rules for Examination of temporary repairs in way of the forward end of No.1 D.B. tank (S.R.L. items).

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

S.R.L. (No.234):

Set up keel plates Nos.1 & 2 from forward to be renewed and centre girder in way to be specially examined and dealt with as necessary by 4/65.

Now done: Temporary repairs (See Karachi Report No.515) examined and found to remain efficient.

It is submitted that the Owners request to postpone the repairs until August 1965 (due to the dry dock at Karachi not being available) merits the favourable consideration of the Committee.

I recommend that this ship remain as classed ~~with~~ without fresh record of dry docking. subject to keel plates Nos.1 & 2 (from forward) being renewed and centre girder in way being specially examined and dealt with as necessary before September, 1965 and also subject to all other outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

.....(K.D. Boothman).....
Surveyor to Lloyd's Register of Shipping

Date of Committee

FRIDAY 25 JUN 1965

Minute

Amow, subject (hom)
MBS 1.65

FOR CHAIRMAN
CLASSN. CTTEE

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due