

21 OCT 1964

Ship's name

"MANSOOR"

Port

KRH

No.

560

Last survey date 31.7.64.

Class is subject to

- 1) General service pump sea suction valve chest being renewed at next dry-docking or by the end of March, 1965.
- 2) Windlass crankshaft starboard driving disc being renewed by the end of September, 1964 (3 months).

Docking. Wear-down: .105"


Vessel dry docked on account of grounding at Mina Suliman on 27.6.64. Propeller and outside fastenings specially examined and found in good order.

SRL Item No. 2. Windlass crankshaft starboard driving disc now renewed, submitted this item be deleted from SRL.

No. 1 plummer block examined at this time, white metal lining found fractured and holding down bolts and chocks inefficient.

Plummer block re-metalled and satisfactorily re-fitted with its holding down bolts and chocks renewed.

IT IS SUBMITTED that this vessel is eligible to remain as classed, subject as above regarding item 1, without any other special condition.


16.10.64.



© 2020

Lloyd's Register
Foundation