

Ship's name *MANSOOR*

Port *Kuwait*

No. *490*

Last survey date *4/7/64*

Class is subject to

*G.S. pump sea suction valve chest
being renewed at W.D.D by end of March 1965.*

*Wardlas crankshaft - started driving disc
fractured in two places. Repairs effected satisfactorily
and Surveyor recommends Wardlas crankshaft
started driving disc be renewed by end of
Sept. 1964 (3 mos.)*

*It is submitted that this
vessel is eligible to remain
as CLASSED.*

*Subject as above and as
new recommended.*

*Lloyd's Register
28/8/64
Foundation*