

COPY

Ship's name "BOUNDARY"

Port

Drb.

No. 9976

Last survey date 22.9.62

Ship is subject to NONE.

8 - OCT 1962

L. Appendix (as before or none)

Location of present survey (afloat and ~~in~~ drydock)

Examination of temporary repairs to corroded shell plate.

Recommendation

SUBJECT to corroded shell plate at after end of  
after cargo hold (s.s.) being examined and dealt  
with as necessary before loading another cargo.

As Now. Subject

IN S.R.L. APPENDIX.  
(rudder stock twisted 20°)



© 2020

Lloyd's Register  
Foundation