

**Lloyd's Register of Shipping.**

FOUNDED 1760.

RE-CONSTITUTED 1834.

**Certificate of Class**

*Steel Screw Steamer "John Holt"*  
 Official Number 181035 Port of Registry Liverpool  
 Owners John Holt & Co. (Liverpool) Limited  
 Builders, and where and when Built Cammell Laird & Co. Limited, Birkenhead, September 1946.

**REGISTERED PARTICULARS.**Length 370.40 feetTonnage, Gross 3818.33Breadth 52.80 feetDitto under Deck 3033.35Depth 20.85 feetDitto Net 2164.69

**This is to Certify** that this Vessel has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 6<sup>th</sup> September, 1946 in a good and efficient state, and fit to carry dry and perishable Cargoes, and has been **CLASSED** and entered in the **REGISTER BOOK** of this Society, with the Character **100A1**



with freeboard FITTED FOR OIL FUEL 9.46 FLASH POINT ABOVE 160°F.

**subject to Periodical Surveys as required by the Rules.**

The class is assigned and maintained upon the understanding that cargo battens will be fitted at the first available opportunity.

**THE FREEBOARDS FROM THE DECK LINE ARE AS FOLLOWS:—**Tropical 1 feet 11 <sup>3</sup>/<sub>4</sub> inches (T).Winter North Atlantic } 1 feet 1 inches (WNA).Summer 1 feet 5 <sup>1</sup>/<sub>4</sub> inches (S).Allowance for fresh water for all freeboards } 5 <sup>1</sup>/<sub>2</sub> inchesWinter 1 feet 10 <sup>3</sup>/<sub>4</sub> inches (W).**Witness my hand,**

*P. E. Clement*  
 Secretary.

*R. H. A. A. A.*  
 Chairman.

71, Fenchurch Street, LONDON, 12<sup>th</sup> November, 1946

N.B.—If the vessel herein named proceed to sea with a less freeboard than that assigned, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”



KAYO - MATAPAS

9600 - 976400 - 816400  
004918 - 004926 - 0096



© 2020

Lloyd's Register  
Foundation