


LLOYD'S REGISTER OF SHIPPING



Port.....

H A L T A

Date.....

5th November, 1963.

This is to Certify *that I have surveyed part of the machinery*

of the **N.S. "ALVA CAPE", 11232** *gross tons* **of London**

for advancement of Continuous Survey, Screwshaft Survey, Auxiliary Boiler Survey, Repairs and Condition of Class, on the 26th July, 1963 and subsequently, whilst the ship lay afloat and in drydock at this Port,

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following

survey records assigned

CSM (with date) upon completion; TSCL 7/63; ABS 7/63, when the safety valves of both boilers have been adjusted under steam and the oil burning system and remote controls examined in accordance with the Rules. Also without special condition regarding the Main Engine Nos. 1 & 2 cylinder liners and the Main Engine forward sea water circulating pump discharge valve and the auxiliary condenser overboard discharge valve, Parts now examined: but subject to any other conditions of class being dealt with as previously recommended.

Main Engine

All six cylinders, pistons and rods.

All valves and gears.

Nos. 1, 2, 3, 4 & 6 Centre and Nos. 1, 2, 3 & 4 side connecting rods, crossheads, bearings and guides.

Nos. 1, 2 & 6 Centre crankpins & bearings.

Nos. 1, 6 & 7 Journals & bearings.

Forward, centre and aft main engine driven scavenge pumps.

P.T.O.

R. Davis

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CSM Continuous Survey of Machinery
DBS Donkey Boiler Survey
ES Engine Special Survey

MBS Main Boiler Survey
OF Fitted for oil fuel (date) FP above 150° F.
SGS Steam Generator Survey
SPS Steampipe Survey

TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Other Items
Starboard outboard oil fuel heater.
steering machinery.
Windlass.
Propeller and outside fastenings of sea connections.
All sea connections.
Screwshaft and continuous liner.
Port and Starboard auxiliary boilers.

© 2020

Lloyd's Register Foundation