

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex  
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

14th December, 1964

Dear Sirs,

C  
ANS/RW

m.v. "ALVA CAPE"

Reverting to your letter dated the 13th ultimo, I have to inform you that the Report of the survey carried out by the Society's Singapore Surveyors on the 13th and 14th ultimo, has now received the consideration of the Committee.

At that time, Metalock repairs were effected to the main engine No. 2 cylinder liner, which was found to be cracked, and it was recommended that these repairs should be examined by the end of May, 1965.

The Surveyors also reported that temporary repairs were effected to the main engine forward salt water circulating pump discharge valve, which was found to be cracked, and it was recommended that this valve should be renewed at the earliest opportunity, and by the end of May, 1965.


The Committee have continued the vessel's class subject, inter alia, to these matters receiving attention by the time stated.

Yours faithfully,

T.S. due 4.65

Deputy Clerk to the  
Classification Committee

The Shipping Management S.A.M.,  
27, Boulevard d'Italie,  
Boite Postale 130,  
Monte Carlo,  
Monaco



© 2020  
Lloyd's Register  
Foundation

005056-005060-0105