

11 DEC 1964

Ship's name Alva Cape

Port Sng.

No. 17895

Last survey date 17.11.69

Class is subject to

main engine No 3 cylinder liner (matedlock
8.64) being specially examined and
dealt with as necessary by 11.69

SRL above C/E states as liner
was leaking this liner was
changed 9.64.

m.e. No 2 ^{cyl} liner found cracked
now repaired by matedlock (11.69)
surveyor recommends be re-examined
by 8.65.

m.e. forward s.w. circulating pp
discharge valve found cracked
now repaired by cement box
surveyor recommends be renewed
at earliest opportunity or by 8.65

It is submitted that this
vessel is eligible to remain
as CLASSED.

subject as recommended without
subject to above



© 2020

Lloyd's Register
Foundation