

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

JULY
5th ~~MAY~~, 1963.

Telephone: ROYal 9166
Telex No.: 24305

Dear Sirs,

M.S. "ATHELSULTAN"

C.
MWK/DET

The Society's Surveyors at Visakhapatnam have reported that this ship was examined last month at which time cracks were found in the main engine frame between Nos. 3 and 4 units.

Repairs were carried out by welding and following this survey it was recommended that these repairs be re-examined before the end of next month, and the Committee have continued the class subject to this matter receiving attention by the time stated.

I shall be glad to learn, in due course, what arrangements you propose to make to deal with this condition of class.

Yours faithfully,

Deputy Clerk to the
Classification Committee

The Athel Line Ltd.,
Bowater House East,
68, Knightsbridge,
LONDON, S.W.1.



© 2020

Lloyd's Register
Foundation

005069-005074-0086