



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Lloyds Bank Chambers,

Albert Road, Middlesbrough

Telephone: Middlesbro' 43431-2

RECEIVED

13th April, 1951.

19 APR 1951

Reference

Ship..

Ans.....

Dear Sir,

M.V. "ATHELSULTAN".

With reference to your letter of the 13th instant, we send you herewith print of Drawing No, 1241, "Steam, Exhaust and Air Pipes", Sheet B, showing the modification made to the fire extinguishing in way of the oil fuel unit which was moved to the Engine Room, and we would mention that this print also shows the fire extinguishing pipes in the purifier room. Also enclosed is the print "Fire Extinguishing Arrangement" giving the number, capacity and position of the chemical fire extinguishers as desired.

We regret that these points were inadvertently omitted to be sent with our Report 4b.

Yours faithfully,
The Surveyors,

Per :-

The Secretary,
LONDON.

Encls:-



© 2020

Lloyd's Register
Foundation

005069-005074-0094

213

For Engineer Surveyors (F.E. Rpts) to note

Noted. em 26/4/51.

THE UNIVERSITY OF CHICAGO

With reference to the above stated agent for the purpose of
 obtaining the same.

located and location of the chemical line ex-
isting while extinguishing arrangements" listing the
arrangements in the building room. "Also enclosed
only to effect this line also across the line
that this meter was moved to the engine room.
Also moved to the line extinguishing in way of
extinguishing in pipes, Street B, showing the
arrangements for the extinguishing of the meter
No. 1247.

$$V_{\text{eff}} = V_{\text{eff}}^{\text{eff}} + V_{\text{eff}}^{\text{eff}}$$

1891
1892

© 2020

Lloyd's Register
Foundation