

"EMPIRE SERVICE"

Lithgow's No. 982.

The Electrical Equipment of this vessel has been fitted on board under special survey in accordance with the requirements of the M.O.W. T., tested under working conditions and found satisfactory.

The materials and workmanship are good.

The report is in the hands of the Builders for signature.

Last date of survey - 5th July, 1943.

J. M. Gardiner.

5th July, 1943.



© 2020

Lloyd's Register
Foundation

005069-005074-0129

Switches, Circuit Breakers and Fuses, are they as per Rule Yes, are the fuses an approved type Yes

STYRENE

330, 011, 010, 006.

© 2020

Lloyd's Register
Foundation

CHOT, TONG, TONG