

DD 5167 - 205173 - 0096

4 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

"EMPIRE ALD GATE"

Rpt.

Off. No. 55903

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Oil fuel burning appliances fitted.
S due 7.48 now examined.
New bronze propeller fitted.
Stern bush rewooded.

IT IS SUBMITTED that this vessel is eligible for the Record S 5.47.

Note in Register Book:-

Fitted for oil fuel 6.47, F.P. above 150° F.

*It is concluded that the funnel damper has been removed or fixed in the open position, but the Surveyor should confirm this.

* removed See Off letter 21/8/17

© 2020

Lloyd's Register
Foundation

11. 8. 47.