

Has Shaft now fitted been previously used?

Has Shaft now examined/fitted a continuous liner?

MAIN ENGINES (Recip. Steam or I.C.)

The class is subject to the starboard boiler main and auxiliary feed valve castings being dealt with by the end of July 1958, and to the main engine IP and LP slide valves being examined and dealt with by the end of July 1958, also to the stoppered tubes in all boilers being dealt with as necessary at the next MBS.

4E

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor..... 11.5 SEP 1958

SHIP'S NAME..... MIRIELLA..... REPORT..... Nap..... No. 6666

MBS due 11.58, partly held now.

Docking.

SRL: The above items dealt with.

IT IS SUBMITTED this vessel is eligible to remain as classed with fresh record of MBS 8.58 when the survey has been completed as per this report, without special condition.

12.9.58

005187-005193-0106