

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex  
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

25th February, 1966.

C.  
DD/DET

Dear Sirs,

M.S. "PHOENICIAN STAR"

When this ship was at Karachi between the 30th December and 14th January, the Surveyors reported that they had examined a temporary repair to an armature shaft which had been executed by the ship's staff, and whilst considered efficient meantime, it was recommended that the forward diesel generator armature shaft be renewed on the ship's arrival in Japan.

The Committee have continued the ship's class subject to this matter receiving attention by that time, and I shall be glad if you will inform the Owners accordingly, it being concluded that they have made the necessary arrangements in this respect.

In order to complete the Auxiliary Boiler Survey which became due at the end of December last, the lower auxiliary boiler remains to be examined in its entirety, and its safety valves adjusted. Please inform the Owners accordingly and ascertain and let me know their intentions for the completion of this survey. / /

Yours faithfully,

pro Clerk to the  
Classification Committee

The Surveyors,  
HONG KONG.  
c.c. KOBE

© 2020

Lloyd's Register  
Foundation

005187-005193-0248