

COPY LLOYD'S REGISTER OF SHIPPING



5989

Port Yokohama
Date 7th June, 1965

we

This is to Certify *that I have*

surveyed the **N.S. "PHOENICIAN STAR"** **4925** Gross tons **of Panama**

whilst afloat and in drydock of Yokohama Dockyard, Yokohama, on 26th May, 1965 and subsequently on account of Docking Survey, Annual Load Line Survey, Conditions of Class, Damage stated to have been caused (see overleaf), Repairs (wear & tear) and Commencement of Special Survey (C) due 8.65

we are

and that *I am* transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by ~~us~~ ^{our} ~~me~~ have been completed to ~~my~~ ^{our} satisfaction, also that *I am* ^{we are} recommending that she be continued as now classed with fresh record of D.S. 5.65 and to have the Notation of S.S. (with date) when the survey has been completed, without special condition to shell plates SB, 9, 18, K9 (SSa), F6, G7 (PSa), H & I strakes in way of Pro.68(PB), 71/73 (SS) and upper deck plating but subject to renewed stringer plating over midship deep tank (P & S) and Fwd. engine room bulkhead in way to be tested prior to the completion of Special Survey, meantime tank top not to be subjected to pressure.

P.T.O.

W. Weiler *B.R. Mac Lennan*
W. WEILER & **B.R. MAC LENNAN**
Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BiS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	CSH	Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B) 3.65 KOB

005187-005193-0285

Damages: Stated that date and cause are unknown.

How done for Special Survey:-

Examined internally:

- 1) No.1 d.b. tank) incl. cement on bottom shell.
- 2) No.6 d.b. tank
- 3) F.P. void space.
- 4) F.P. spaces (except oh. locker)
- 5) A.P. tank.
- 6) A.P. spaces. *loc*



© 2020

Lloyd's Register
Foundation