

COPY

# LLOYD'S REGISTER OF SHIPPING

5989



Port YOKOHAMA

5th June 1965

**This is to Certify** *that I have surveyed part of the machinery*  
of the **M.S. "PHOENICIAN STAR"** **4925** *Gross tons* of **Panama**  
**(ex "SAN FERNANDO")**  
for **Docking; Advancement of CSM; TS(CL) and Repairs**  
on the **26th May 1965** and subsequently  
whilst the ship lay in drydock and afloat at **Yokohama**


*and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned* **CSM (with date) on completion of survey and TS(CL) 5/65**  
subject to any outstanding condition of class being dealt with as previously recommended.

Parts now examined:—

DOCKING & TS(CL):—

**Propeller, sternbush, sea connections and fastenings.  
Screwshaft.**

CSM:— **M.E. No.1 unit cylinder, pistons & rods, transverse beam, pins, bushes & bottle guides and valves & gears.  
M.E. No.2 journal & bearing.  
M.E. driven salt water cooling pump.  
M.E. driven jacket cooling water pump.  
M.E. driven L.O. pump.  
Both Feed water pumps (PS)  
Fwd. Inbrd. aux. diesel generator engine (SS) in its entirety.**

  
**R. TANEDA**

*Surveyor to Lloyd's Register of Shipping*

ABS Auxiliary Boiler Survey  
CSM Continuous Survey of Machinery  
DBS Donkey Boiler Survey  
ES Engine Special Survey

MBS Main Boiler Survey  
OF Fitted for oil fuel (date) FP above 150° F.  
SGS Steam Generator Survey  
SPS Steampipe Survey

TS Tailshaft Survey  
TS(CL) Tailshaft Survey—Continuous Liner  
TSN Tailshaft renewed  
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."