

Bakkeveld



Lloyd's Register of Shipping,

14, Cross-shore Street,

Greenock, 23rd September, 1919.

Encl: 1.

ANS.

~~D.S. 404~~

Reference
"A".

Dear Sir,

With reference to your letter of 19th inst. with regard to the 1st Entry Report No. 17508 on the Steamer "BACKWORTH", I beg to state that the floors in the engine space are .32 as stated on the Report, but in the succeeding ships they will be .38 (See copy of letter regarding these floors received by Messrs Dunlop, Bremner & Co., Ltd., from Messrs S. P. Austin & Son, Ltd.); built pillars in forward holds are as per approved plans; and the stiffeners on the fore peak bulkhead should be 7x 3 x 40 bulb angle, and not 7 x 3 x 34 as stated on my Report, which I regret was made in error.

I am, Dear Sir,
Yours faithfully,

Robert Dunson

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

005187-005193-0482

005187-005193-0485

Lloyd's Register of Shipping

14, Cross-street, London

Greenock, 24th September 1891

Dear Sir,

With regard to the... of 1891...
regard to the... of 1891...
"MARWORTH", I... to...
... of 1891...
... of 1891...

Referred to the Chief Map Surveyor

W.M.
SEP 24 91
W.M.
26.9.91
Robert...

The Secretary,
Lloyd's Register of Shipping



© 2020

Lloyd's Register Foundation