

Gross Tons:- 2481.

Upper Dk. Dk. Beam, A

Surveyors

Received from Chief Surveyors

NAME STEEL & S. "BACKWORTH" Report Greenack. No. 17508.

For the CHIEF SHIP SURVEYOR

a cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/39.)

Survey

When due

*100 A 1. (steel)

1 Dk. (steel)

Cell DB 260' 669 E. FPT 72 E. APT 170 E.


FK. 6 BH. pt.cem. Lloyd's A & C.P. P 32', B 80', F 33'

M. ats

22.8.19

It is concluded, the floors in engine space, the built pillars in
forward holds, and the stiffeners on the fore peak bulkhead are as approved
at the Surveyors should be requested to state if this is so.

*See also
27.9.19.*



Lloyd's Register
Foundation

005187-005193-0487

Plate.)