

N/N EVER-SURE



Lloyd's Register of Shipping,

95, Bothwell Street,

Glasgow, C.2. 2nd November, 1940.

Dear Sir,

I have to acknowledge receipt of London letter of the 29th ultimo regarding Glasgow First Entry Report No. 62870 on the Steamer "BURNSIDE" and have to state in reply that, with reference to paragraph 1 (b) of the Rules, cement has not been fitted in the boiler room double bottom tank, but that the scantlings have been increased from .45 to .55, as indicated on the approved Midship Section.

I have also to state that the thickness of the second deck plating abreast the boiler casing is .50 in accordance with the plan of Second Deck Amidships forwarded with the First Entry Report.

I am, Dear Sir,
Yours faithfully,

T.R. McIlwain

The Secretary,
GLASGOW.



© 2020

Lloyd's Register
Foundation

-B-
Noted
f.e.d.

[Handwritten signature]

[Faint handwritten text]

[Faint handwritten text]

[Faint, mostly illegible typed text, possibly bleed-through from the reverse side of the page]

• Odd, redwood has 3.0 wood