

10 AUG 1959

Received from Chief Ship Surveyor.....

SHIP NAME "HELICINA" REPORT Lon. No. 140694
VC

Standing Conditions of Class: NONE

L. Appendix. (As before ~~XXXXXX~~)

Surveys due: SPECIAL SURVEY (D) due 10.59 Commenced Lon. 9.58

Location of Present Survey: (~~XXXXXXXXXX~~ in dry dock)

Docking.

Special Features:

Interim Certificate in order (Yes-~~No~~-None)

~~Ins Outstanding: (If any for S.S.)~~

FOR PORTION OF SURVEY HELD:- See Rot. report 46133.

to be completed by:

Recommendation: SUBMITTED record of 'DS. 7.59' be assigned as recommended.

DS. 7.59.

S.S. PART HELD. ✓

IN S.R.L. APPENDIX.

Indents in side shell plating (s.s.a) and in way of Nos 5 & 6 cargo tanks (p.s) and bottom forward.

OFFICE NOTE.

Structural arrangements in order - 5.12.55
Shell and deck modified - Nwc. 10.55

Handwritten initials and date: 31/7-59



© 2020

Lloyd's Register Foundation