

M.S. HELICINA

IT IS SUBMITTED the OWNERS
Surveyors be informed in reply to ~~their~~ letter of 16th July 1959
that, according to the records in this Office, the
following remains to complete the Continuous Survey
cycle of the machinery at this date. It should be
borne in mind that delay in completing the Survey
may involve the examination of additional items.

Examine:- Both main alternators, 2nd 9/58
Intermediate Shafting & bearings,
Emergency Propelling set,
General Service Pump,
Oil Fuel Transfer Pumps,
Pumping arrangements,
3 Forced draught Fans,
Distiller,
Bulkhead Stops and manœuvring Valves,
Combustion Control air Compressor & Receiver,
Part aux Electrical Equipment,
Steering gear,
Windlass,
Holding down Bolts
Fire Extinguishing arrangements. ✓

vessel's class is at present subject to the Starboard
& low injection valve chests being specially examined
the next special survey.



Lloyd's Register
Foundation