

10 AUG 1959

4E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME "HELICINA" REPORT LON No. 140694

The Class is subject to the Port and Starboard High & low main sea injection Valve chests being specially examined at the next Special Survey and to the Starboard main Condenser being tested and repaired as necessary at port of discharge at the end of June 1959 (1 month's limit), also to the starboard main circulating Pump motor shaft being repaired or renewed before vessel leaves the UK and the Starboard Generator Condenser and aux boiler being repaired before vessel leaves UK.

Docking
SRL items Starboard Main Generator Condenser, Starboard circulating Pump and aux Boiler repairs have now been dealt with and the Surveyor submits these items could be deleted from SRL list.

It is submitted that this vessel is eligible to remain as **CLASSED**. Subject to Starboard High & low injection valve chests being specially examined at next special Survey but without other special conditions.

[Signature]
10.8.59

Lloyd's Register
Foundation

005269-005279-0055