

2m.11.35.

1

*fees paid*

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Screw M.S. "SALACIA" Report Gls. No. 58710

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

FIRST ENTRY

When due

100A1 "With freeboard"


2 Dks. and shelter dk. 4th deck in Nos.2 & 3 holds.

Cell. DB 366' 1304t, DTa 27' 777t, FPT 82t, APT 180t.

FK, 7 BH (Coll. BH to Shelter Dk. 6 BH to 2nd Dk.), pt. Cem., Lloyd's

F 31'

O.L. 447.91'



checked by

26 AUG 1937

Date