

5m,11,27.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor 18 JAN 1930

VESSEL'S NAME Steel S.S. "LARISTAN" Rpt. Bdx No. 4026

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

The Bordeaux Surveyor now reports damage sustained to bridge front, upper and lower bridges, deck fittings etc., through heavy weather. Temporary repairs have been effected.

The Surveyor recommends that the vessel be placed in drydock for examination of the bottom, all tanks be tested, the midship structure above bridge deck removed and rebuilt and all piping and electric wiring on deck be placed in order on the vessel's arrival in the Tyne.

The vessel is now under survey at Newcastle.

It is submitted action be deferred pending the receipt of a report from the Newcastle Surveyors.


WRMA.
14.1.30.



© 2021

Lloyd's Register
Foundation

005311-005317-0030