

COPY

Ship's name

Bio 5060

Port

PORT

No.

2489

Last survey date


12.63

Class is subject to

Damage Rps.

Temporary repairs & shaken
windlass & pulley wheel capped
out at Tbdano, examined
by L. A. J. and found to
be efficient. Meanwhile with
recommendation that the windlass
be specially examined and
cleaned with as found necessary
at the Special Survey (due 2/64).

It is submitted that this
vessel is eligible to remain
as CLASSED.



© 2020

Lloyd's Register
Foundation