

COPY

LLOYD'S REGISTER OF SHIPPING



Port Liverpool

31st October, 1960.

This is to Certify that ^{we} ~~I~~ have

part boilers & part
Surveyed ~~the~~ Machinery of the s.s. "RHODESIA CASTLE", 17041 tons gross of

London whilst afloat and in Gladstone Dry Dock, Liverpool,

and that ^{we} ~~I~~ will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by

^{is} ~~me~~ in connection therewith have been carried out to ^{our} ~~my~~ satisfaction; also

that ^{we} ~~I~~ will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book

Starbd. T.S.(C.L.) 9,60 now, and M.B.S. 10,60, on completion,

and that her Machinery Classification Record be continued in the Book.

To complete the survey for fresh record M.B.S. 10,60, the port and Centre
boilers remain to be examined in their entirety, and afterwards these boilers
to be examined under steam, their safety valves adjusted, and the oil burning
system, and remote controls examined and tested.

Parts now examined:

(C.S. Items only)

Port Main Engine.

L.P. Turbine and its flexible coupling.

Starboard Main Engine.

Reduction gearing.

Thrust block, shaft and bearings.

Intermediate shaft and bearings.

Cont. Over.

J. F. Findlay

Engineer Surveyor to Lloyd's Register
J. Findlay (for self & colleagues.)

KEY TO ABBREVIATIONS


ABS	Auxiliary Boiler Survey
CS	Continuous Survey of Engines
DBS	Donkey Boiler Survey
ES	Engine Special Survey
MBS	Main Boiler Survey
MES	Modified Survey of Oil Engines
OF	Fitted for oil fuel (date) FP above 150°F.

SGS	Steam Generator Survey
SPS	Steampipe Survey
TS	Tailshaft Survey
TS(CL)	Tailshaft Survey—Continuous Liner
TSN	Tailshaft renewed
TS(OG)	Tailshaft Survey—Oil Gland

© 2020

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation

