

NO RESPONSIBILITY WILL BE ACKNOWLEDGED FOR ANY CONSEQUENCES ARISING OUT OF STRIKES, LOCK-OUTS, COMBINATIONS OR OTHER LABOUR DISTURBANCES NOR FOR LOSS OR DELAY DUE TO HOLIDAYS, BAD WEATHER, FIRE, ACCIDENT OR ANY OTHER CAUSE BEYOND THE COMPANY'S CONTROL OFFERS FOR DRY DOCKING ARE SUBJECT TO DOCK BEING AT LIBERTY. ALL TRANSPORTING AT OWNERS RISK.

R & H. GREEN AND SILLEY WEIR LTD.

SHIP REPAIRERS & ENGINEERS.

TELEGRAMS:
REPAIRS, ALDOCK, LONDON.

TELEPHONE NUMBERS:
GENERAL OFFICES: ALBERT DOCK 2121 (5 LINES)



Works:

WALL YARD: EAST 4171 & 4172 SURREY DOCKS, BERMONDSEY 3187 & 3188
ALBERT DOCK: ALBERT DOCK 1641 (3 LINES) MILLWALL DOCK: EAST 4611 & 4612
WALWORKS ROYAL ALBERT DOCK: ALBERT DOCK 1506 TILBURY DOCK: TILBURY 53 & 113

CITY OFFICE: 130-132, LEADENHALL STREET, E.C.3.
TELEPHONE AVENUE 8308 (3 LINES) TELEGRAMS: INTERKNIT, STOCK, LONDON.

Blackwall Yard,
London, E.14.

August 8th. 1934.

OUR REF. JPC/GB

YOUR REF.



Plans
Lloyd's Register of Shipping,
71, Fenchurch Street,
E.C. 3.

Dear Sirs,

S. S. " DRAKE ".

We have been requested by the Owners of the above vessel to cut an opening in the shelter deck between No.2 hatch and the foremast to form a hatchway for baggage etc. This hatch will be battened down at sea.

We enclose print No. 16478, in duplicate, which shews the proposed arrangement.

The Owners also require two coaling ports arranged in each side of the ship, the proposed arrangement being shewn on print No. 16477, in duplicate, herewith.

We shall be glad of your early consideration and approval of these plans.

Yours faithfully,

R. & H. Green and Silley Weir Ltd.

J. Campbell

005358 - 00366 - 115

© 2021 Lloyd's Register Foundation

Referred to the Chief Ship Surveyors

A/B

- 8 AUG 1934

REQUESTING EARLY REPLY.

Submitted for approval as indicated

S. I. 8 28

"DRAKE"

Baggage hatchway in shelter deck and two coaling ports on each side of the vessel

Ltr. 8/8 Ansd. 9/8

2 plans
2 plans & p.c. handed Lon. Surs.



© 2021

Lloyd's Register Foundation