

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... 10... When handed in at Local Office... 9th Oct 34 Port of LondonNo. in Survey held at London Date, First Survey 5th July Last Survey 3rd Oct 1934

Reg. Book. 75163 on the Wood, Iron or Steel DRAKE (No. of Visits 14)

TONNAGE:— Gross 1656.58 Built at Ayr By whom Ailsa P.B.C. Co. Ltd When 1922 2nd month
UNDER DK. 1048.55 Owners' Address Government of Zanzibar
NET 830.64 Managers Port belonging to Zanzibar

Surveyed Afloat in Dry Dock? Yes Name of Dock Blackhall Dry Dock Destined Voyage Zanzibar

WB=CellDBoD Ba feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 100069 Port Lon

CHARACTER.	Machinery and Boiler
For Special Survey.	(including date of N.B., if any).
Date of last Survey and of Periodical Surveys.	
+100A1	+LME 830
Plating with	BS 10, 33.
prebend.	
7.32	
P.S. 102-30.	T.S. 7, 32/24

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition, alterations & change of Owners. (See also correspondence attached to deferred reports) 1st Special Survey due 2, 34

Condition now done:— Vessel placed in dry dock & the bottom & rudder cleaned, examined & coated.

The weather decks, casings, ventilation, hatches & hatchways, steering gear etc examined & found satisfactory.

The hold & tween decks etc examined generally & found satisfactory.

Nothing has been done at this time towards the 1st Special Survey due 2, 34, see endorsement attached to deferred reports.

Transverse repairs. Several hatch covers renewed & minor repairs effected (P.T.O.).

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Good	✓	(State if on Felt).
Caulking of Decks	✓	✓	When put on, Month
Coamings	(Part 44) ✓	✓	Year
Beams & Fastenings	(Part 44) ✓	✓	Boats
Outside Plating	✓	✓	Masts, Yards, &c.
in way of sidelights	✓	✓	Condition, how ascertained
Breasthooks	✓	✓	(State if wedges removed)
Transoms	✓	✓	Sails
Frames	(Part 44) ✓	✓	Equipment letter
Reverse Frames	✓	✓	Anchors, No. of
Longitudinals	✓	✓	Chain Locker
Transverses	✓	✓	Cables (State if now ranged)
Floors	✓	✓	length mean diamr.
Keelsons	✓	✓	(on board) size
Stringers	(Part 44) ✓	✓	Rule length
Inner Bottom Plating	✓	✓	Hawser & Warps
	and found efficient? ✓	✓	Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1, 24," or "to remain as classed and to have record of survey, 1, 24, and the notations of ss No. 1-24 and ptd 24, &c."

This vessel is eligible, in my opinion, to remain as classed without fresh record of survey.

Survey Fee (per Section 20)	ALTERATIONS	10 : 10 0	Fees applied for,
Special Damage or Repair Fee (if any)			10 OCT 1934
Travelling Expenses (if chargeable)			Received by me,
Second Surveyor's Fee (if any)			18/10/34 38W

Committee's Minute TUE. 23 OCT 1934 TUE. 18 DEC 1934

Character Assigned Deferred for 16.3

W. T. Hudson
Surveyor to Lloyd's Register of Shipping.
Lloyd's Register Foundation

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

A new Hatchway fitted in way of foremast, coaling doors fitted (P.S.) through shell into upper two decks amidships, and a new deck house & deck fitted over No 3 Hatch, all these alterations carried out in accordance with the approved plans, three in number, which are returned herewith. Workmanship & materials good.

It is stated that the vessel will be named "AL SAID" on her arrival at Zanzibar whether she is now proceeding.

W. J. H.

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.



Lloyd's Register
Foundation