

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
                          Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

7th November 1962

C  
HWM

Dear Sir,

Motorship "RANA"

It is reported in the shipping papers that this ship recently developed a leak and subsequently sank. In the circumstances, I shall be obliged if you will furnish me with details of any information which may reach you regarding this casualty.

I should perhaps add that this ship was under the inspection of the Surveyors at Groningen in September/October last and the Surveyors recommended a record of Docking 9.62 TS (OG) 10.62 subject to the tank top plating of No.2 D.B.tank starboard side (temporarily repaired 1.62) and indented bottom shell plate starboard side B5 (from forward) being specially examined and dealt with as necessary at the next Special Survey.

Yours faithfully,

Deputy Clerk to the  
Classification Committee.

P.H. van der Weel Esq.,  
ROTTERDAM.



© 2020

Lloyd's Register  
Foundation

005367-005376-1-1-13