

by Chief Ship Surveyor

Received from Chief Ship Surveyor

175 FEB 1921

EL'S NAME *Steel S.S. "MARY AUSTON II"*

Rpt. *Low*

No. *84005*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey *Last Entry*

See Letter 21.2.21

Before this case receives consideration the Surveyors should be requested to state whether a keel anchor of proper weight and test has been supplied.

They should also be informed that the Health Surveyors report the forward main deck to be leaking and that the vessel is returning to the Builders Yard to be put in order.

Classing Cl-
W.Ds: - *1572421*



© 2021

Lloyd's Register
Foundation

005377 - 005386 - 0139