

25 FEB 1959

Received from Chief Ship Surveyor

PS NAME "WILLIAM CHARLICK 4". REPORT Dja. No. 5575.

standing Conditions of Class: Subject to shell plates B.4 & C.5 (p.s.f) and G.2 (p.s.a) being examined and dealt with as necessary, also to shell plate No.C.2 being specially examined and dealt with as found necessary by the S.S.

ACTION IS DEFERRED for S.S. & for examination in drydock after grounding.

Postponement of Class (B) (As before ~~on 18.2.58~~)

Days due: SPECIAL SURVEY (C) became due 5.58. Postponement until 1.59 approved 18.2.58. Further postponement until 2.59 approved - see letter dated 6.1.59.

Place of Present Survey: (Afloat ~~and in dry dock~~)

Further examination afloat after grounding.

Special Features: Owners state ship proceeding direct to HongKong where the S.S. will be carried out.

Interim Certificate in order (Yes-~~No-None~~)

Outstanding: (If any for S.S. or A.S.) All items.

to be completed by:

Recommendation: SUBJECT as above, but ACTION SHOULD CONTINUE TO BE DEFERRED for S.S. & for examination in drydock after grounding.

SUBJECT.

IN S.R.L.  
Drydocking (grounding).

S.R.L. APPENDIX.  
Indents in shell plating (p & s).



© 2020

Lloyd's Register  
Foundation

005387 - 005396 - 0009