

of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides stated in the body of the report, should be briefly summarised at the end of the report. State also the dates and of any letters respecting this case.

s.s. Hkg. 5/54
Reclassified 5/54

The class is subject to the independant driven main circulating pump being specially examined before the end 12.58.

4E

5 MAR 1959

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME..... WILLIAM CHARLICK 4 REPORT..... Djk. No. 5575

S.R.L. The above item examined under working conditions, found satisfactory and the Surveyor recommends the independent driven main circulating pump be examined on arrival at Hong Kong, and by 2.59.

IT IS SUBMITTED that this vessel is eligible to remain as CLASSED, subject as now recommended.



ADW
2.3.59
© 2020

Lloyd's Register
Foundation

005387-005396-0014

IRS (W & T): Two new turns of packing fitted to stern gland.