

Charges to pay

POST OFFICE



TELEGRAPHS

No. of Telegram

E.24.

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME Steel Se Sa "ARCOONA"

Report Gls

No. 43641

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

re of Survey

1st Entry

When due

This vessel has been built in accordance with the Revised Rules and the Builders have obtained the owner's consent thereto (see letter attached).

✦ 100A.1 (Steel) with freeboard }
2 SKs (ptl)

Subject to the W.T. door on frame 77 being adjusted to give sufficient lap at bottom of frame of door.

Cell D.B 288 878t, F.P.T 97t, APT. 126t.

F.K, T.B.H (Collision B.H to weather SK), Cen, Lloyds A & CP.

F 34'



© 2020

Lloyd's Register Foundation

005387-005396-0016